


From: [Downham, Todd](#)
To: [Coltrain, Katrina](#)
Subject: FW: Wilcox Figure
Date: Monday, August 24, 2015 2:11:30 PM
Attachments: [image001.png](#)

Katrina,
Below is a Google Earth screen shot of the former tank location I referred to in my previous email (below).
Hope this helps.
Thank you.
-Todd



From: Downham, Todd
Sent: Friday, August 21, 2015 5:24 PM
To: 'Coltrain, Katrina'
Subject: RE: Wilcox Figure

Katrina,
There is also the property owned by Mary Nealey that should be included. It is south of the White property, west of Chapman. This is a very overgrown area that will definitely need brush hog action to gain access to. The Southwestern-most large storage tank was in this area. The tank berm butts up to the Sand Creek channel.
We can talk about this next week.
Have a good weekend.

Todd Downham
Environmental Programs Specialist
Department of Environmental Quality
Site Remediation Section
Land Protection Division
(405) 702-5136
todd.downham@deq.ok.gov

From: Coltrain, Katrina [<mailto:katrina.coltrain@epa.gov>]
Sent: Friday, August 21, 2015 3:02 PM
To: Kady, Thomas
Cc: Downham, Todd
Subject: Wilcox Figure

Tom, you mentioned on the phone today that you would be able to put together a figure of the site that shows the areas you will be investigating and what methods you plan to use in each of these areas. Todd and I are very interested in the figure and would like to have a copy prior to the field work in September. I understand that we may not see the figure until the week of August 31 due to previous field commitments by the team.

Thanks in advance.

Katrina Higgins-Coltrain
Remedial Project Manager
US EPA Region 6
LA/OK/NM Section
1445 Ross Avenue
Dallas, Texas 75202
214-665-8143